

Certificate TW24/00000992



The management system of

Integrated Service Technology Inc.

No.10-1, Lixing 1st Rd., East Dist., Hsinchu City 30078, Taiwan (R.O.C.)

has been assessed and certified as meeting the requirements of

IEC 61340-5-1:2016

For the following activities

IC Diagnosis & Failure Analysis, Reliability Testing and IC Testing Green Product
IC Diagnosis & Failure Analysis, Reliability Testing.
IC Diagnosis & Reliability Testing

ESD Program Manager: Mr. Eric Lin

Further clarifications regarding the scope of this certificate and the applicability of IEC 61340-5-1:2016 requirements may be obtained by consulting the organization.

Lead Auditor: Michael Chiu

Certification Manager: Roger S. Villanueva

This certificate is valid from 03 March 2025 until 01 January 2026

Issue 2. Certified since 02 January 2025

Certified activities performed by additional sites are listed on subsequent pages.

Authorised by

Roger Villanueva

SGS Philippines, Inc.

3/F Alegria Bldg. 2229 Chino Roces Ave. Makati City, Philippines

t 8288 8787 - www.sgs.com



This document is an authentic electronic certificate for Client' business purposes use only. Printed version of the electronic certificate are permitted and will be considered as a copy. This document is issued by the Company subject to SGS General Conditions of certification services available on [Terms and Conditions](#) | [SGS](#). Attention is drawn to the limitation of liability, indemnification and jurisdictional clauses contained therein. This document is copyright protected and any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful.



Certificate TW24/00000992, continued

Integrated Service Technology Inc.

SGS

IEC 61340-5-1:2016

Issue 2

Sites

Integrated Service Technology Inc.
No.10-1, Lixing 1st Rd., East Dist., Hsinchu City 30078, Taiwan (R.O.C.)
IC Diagnosis & Failure Analysis, Reliability Testing and IC Testing Green Product

Integrated Service Technology Inc.
No.19, Puding Rd., East Dist., Hsinchu City 300047, Taiwan (R.O.C.)
IC Diagnosis & Failure Analysis, Reliability Testing.

Integrated Service Technology Inc.
4F., No. 669, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan (R.O.C.)
IC Diagnosis & Reliability Testing



This document is an authentic electronic certificate for Client' business purposes use only. Printed version of the electronic certificate are permitted and will be considered as a copy. This document is issued by the Company subject to SGS General Conditions of certification services available on [Terms and Conditions](#) | [SGS](#). Attention is drawn to the limitation of liability, indemnification and jurisdictional clauses contained therein. This document is copyright protected and any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful.

